Communications Pte Ltd

12 April 2009

Subject : **Gaylin International Pte Ltd Reducing The Green House Gas & CO2 For The Environment**

Objective : **To Improve Energy Efficiency and Conservation With SolaCoat**

Gaylin International Pte Ltd
No. 7, Gul Avenue, Spore 629651
Tel : 65-6861 3288
Fax : 65-6861 5433

Communications Pte Ltd

Measurement Equipments deployed in this Project

1) Digital Thermometer from Fluke

2) Thermal Imager from Flir

3) Outdoor Mercury Thermometer – To Track the Ambient Temperature

Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

SolaCoat Applications:

Before **After**





Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

SolaCoat Applications:

Before

After

Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Picture / Thermal Visual before SolaCoat Applications





Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Picture / Thermal Visual before SolaCoat Applications





Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Picture / Thermal Visual before SolaCoat Applications





Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Picture / Thermal Visual before SolaCoat Applications



Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Thermal Visuals

Before SolaCoat



After SolaCoat



Before SolaCoat



After SolaCoat



Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Thermal Visuals

Before SolaCoat



After SolaCoat



Before SolaCoat



After SolaCoat



Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Thermal Visuals

Before SolaCoat





After SolaCoat



Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166

Communications Pte Ltd

Roof Temperature Before and After SolaCoat Illustrations





Block 5004 #05-05 Ang Mo Kio Ave 5 Techplace II Singapore 569873 Tel: 64846966 Fax: 64846166